

**ITSDF B56.1-2009
ERRATA
23 February 2010**

An editorial error was made in ITSDF B56.1-2009. Correction should be made to your copy. The corrected version of the standard was posted 23 February 2010 on www.itsdf.org

<i>Page</i>	<i>Location</i>	<i>Change</i>
45	7.29.1 (d)	“The overhead guard shall not extend over the operator under all normal operating circumstances...” should be “The overhead guard shall not extend over the operator under all normal operating circumstances...”