

ANSI/ITSDF B56.1-2012
ERRATA
15 August 2012

An editorial error was made in ITSDF B56.1-2012. Correction should be made to your copy. The corrected version of the standard was posted 15 August 2012 on www.itsdf.org

<i>Page</i>	<i>Location</i>	<i>Change</i>
51	7.37.1 (e-g)	<p>The following three paragraphs were inadvertently omitted :</p> <p>“(e) when controls are supplied for use on the elevating platform, they shall be readily accessible to the operator and protected from damage and inadvertent actuation. Provision to shut off power to the truck shall be provided. An emergency lowering means operable from the ground shall be provided for overriding the controls on the platform.</p> <p>(f) hydraulic or pneumatic hoisting systems shall include means to prevent unintended descent in excess of 0.6 m/s in event of a hose failure.</p> <p>(g) a structural safety factor of not less than 3 to 1 based on the minimum yield strength of the materials used for all load supporting structural elements and platform attachment means.”</p>